



GROUND SAFETY RECOMMENDATION


LIN PIAZZALE OVEST: CANCELLAZIONE VIABILITA' IN CORRISPONDENZA IHP K1

Causa modifiche alla segnaletica orizzontale in GA2, connesse al potenziamento capacità elicotteri, è stata cancellata DEFINITIVAMENTE la viabilità in corrispondenza dell'IHP K1 che consentiva l'attraversamento della APN TWY "Y" da GA1 a GA2 e viceversa.

L'attraversamento in quel punto costituisce una TWY Incursion.

Rimangono attivi i due attraversamenti situati al centro del piazzale Ovest e in prossimità di IHP N1.

La figura sotto riporta il nuovo layout del piazzale Ovest di Linate:



Be safe at all times!

Assicurati che questa Ground Safety Recommendation sia ben visibile nei luoghi di lavoro (Safety Corner)



GROUND SAFETY RECOMMENDATION


LIN WEST APRON: CANCELLATION VEHICULAR ROAD NEXT TO IHP K1

Due to changes in the markings in GA2 area, related to the improved helicopter capacity, the vehicular road CLOSE to IHP K1, that allowed the crossing of APN TWYY from GA1 to GA2 and viceversa, was cancelled.

Apron crossing in this point is classified as a TWY Incursion.

The two intersections located in the middle of the West Apron and next to IHP N1 are still active.

The picture below shows Linate West Apron new layout:



Be safe at all times!

Be sure that this Ground Safety Recommendation is published and visible in your Safety Corner