




GROUND SAFETY RECOMMENDATION

FAILURES TO YIELD RIGHT OF WAY

In the last three years, almost one in two failures to yield right of way occurred in the section of road parallel to the taxi Charlie that passes next to fingers. Given the high congestion in that area due to the intense movement of AA/CC and vehicles, it is essential to adopt the utmost caution: **always respect traffic regulations, especially when AA/CC are taxiing in or out from stands.**



NOTE:

- ✓ Attention to the movements of AA/CC in push back from stands equipped with fingers;
- ✓ Always give way to AA/CC in movement, in tow or preceded by a follow-me;
- ✓ Pay attention to the General Aviation AA / MM taxiing from the November;
- ✓ Respecting speed limits allows you to keep the situation under control and arrive on time whatever your destination!

Pay maximum attention to AA/CC with beacon on: if you are not sure of the direction of an A/C, wait in a safe position until you are sure you will not interfere with its manoeuvre.

Be safe at all times!

Make sure that this Ground Safety Recommendation is prominently displayed at your workplace (Safety Corner)